

| _ | Application No. | Applicant(s) | |
|---|-----------------|--------------|--|
| | 10/671,159 | ITO ET AL. | |
| | Examiner | Art Unit | |
| | Tuvet Vo | 2821 | |

| SEARCHED | | | |
|-----------|----------|-----------|----------|
| Class | Subclass | Date | Examiner |
| 315 | 82 | 9/30/2004 | τv |
| | 77 | . 1 | |
| | 291 | | |
| | 307 | | |
| | 312 | | |
| V | 324 | | |
| 362 | 800 | | |
| | 802 | | |
| | 801 | / | |
| V | 806 | <u> </u> | V |
| 361 | 90 | 3/9/05 | N |
| 1 | 91.1 | · | |
| | 91.2 | | |
| \bigvee | 93.7 | \bigvee | V |

| INT | INTERFERENCE SEARCHED | | | | |
|-------|-----------------------|---------|----------|--|--|
| Class | Subclass | Date | Examiner | | |
| 315 | 291,367 | 3/15/05 | N | | |
| 361 | 91.1 | . 1 | 1 | | |
| 362 | 800 | V | | | |
| | | , | | | |
| | | | | | |

| | SEARCH NOTES (INCLUDING SEARCH STRATEGY) | | | | |
|--------------------------------------|---------------------------------------------|---------------------------------------|--|--|--|
| | DATE | EXMR | | | |
| · detect lamp malfunction/inoperated | 9/30/2004 | τv | | | |
| UPDATED SCARULT | 3/09/05 | TV | | | |
| | | • | | | |
| | | | | | |
| | | · · · · · · · · · · · · · · · · · · · | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |